CC6263

Posted on 13.07.2023 by Jennifer Curran

Category: Cabin Crew

Report TitleFatigue due to inadequate cabin crew rest provision

Initial Report

CHIRP

My operator operates aircraft with no cabin crew bunks. The provision for cabin crew rest is taken on aircraft jump seats that are located close to aircraft doors and in particular passenger aisle areas. This means that crew whilst taking rest are constantly disturbed, on my flight a passenger fell onto a crew member taking rest because the space between the passenger aisle and crew rest is extremely tight and only separated by an extremely thin curtain. On my last flight all of the cabin crew rest periods were disrupted by passengers banging into crew whilst taking rest. We were left fatigued and exhausted and this potentially can have an impact on safe operation by cabin crew.

Comment

Just because a flight is long and there is the time available for a 'rest/break' (in addition to a meal opportunity) this doesn't mean that 'inflight rest' is required to operate the duty.

If the flight duty period (FDP) does <u>not</u> need to be extended then inflight rest is <u>not</u> required. However, in accordance with **UK Retained Regulation ORO.FTL.240 Nutrition**, a <u>meal opportunity</u> is required (although the provision of food is not).

If the maximum FDP does need to be extended, then 'inflight rest' is required.

An aircraft's rest facilities can restrict what routes an aircraft operates due to the length of the FDP. Not all operators have all the below facilities available onboard.

'Class 1 rest facility' means a bunk or other surface that allows for a flat or near flat sleeping position. It reclines to at least 80° back angle to the vertical and is located separately from both the flight crew compartment and the passenger cabin in an area that allows the crew member to control light, and provides isolation from noise and disturbance;

'Class 2 rest facility' means a seat in an aircraft cabin that reclines at least 45° back angle to the vertical, has at least a pitch of 55 inches (137.5 cm), a seat width of at least 20 inches (50 cm) and provides leg and foot support. It is separated from passengers by at least a curtain to provide darkness and some sound mitigation, and is reasonably free from disturbance by passengers or crew members;

Confidential Human Factors Incident Reporting Programme

'Class 3 rest facility' means a seat in an aircraft cabin or flight crew compartment that reclines at least 40° from the vertical, provides leg and foot support and is separated from passengers by at least a curtain to provide darkness and some sound mitigation, and is not adjacent to any seat occupied by passengers.

Please remember that whether at home base or down route, it is an individual's responsibility to manage their rest accordingly and to ensure that they are 'fit' to operate the duty, cabin crew should not be operating when they are unfit to do so. This report states that the crew were fatigued and exhausted, please ensure if you are suffering from the effects of tiredness and/or fatigue, that you report this to your operator.



CC6263

CHIRP